

OPTIONAL ACCESSORIES FOR HUMIDITY TRANSMITTERS

<p>New - probe for compressed air</p>	<p>Order code</p> <p>TxxxxP Hxxx1P</p>	<p>Optional temperature, humidity, dew-point probe designed for compressed air measurement up to 25 bars. Cable lengths 1, 2 or 4m available. Length 110mm, diameter 18mm, G1/2 thread. Available with Tx11P, T3419P and Hxx1P transmitters.</p>
	<p>TxxxxL HxxxxL</p>	<p>Transmitter version with watertight male connector IP67 Lumberg RSFM4 instead of cable gland for easy connection/disconnection of the output. Specify please your order with letter L behind model code - e.g. T3110L or H3020L</p>
	<p>K1427</p>	<p>Female connector ELKA 4012PG7 for TxxxxL, HxxxxL transmitters with male connector Lumberg for easy connection/disconnection of the output. Cable is easily connected to screw terminals of the connector. IP67 protection.</p>
	<p>without LCD</p>	<p>Transmitter version with blind lid without LCD. Specify please the requirement in your order.</p>
	<p>OEM</p>	<p>Transmitters are also available without Comet logo as OEM products. Specify please the requirement in your order. Minimum order of OEM transmitters without Comet logo is 100 pcs.</p>
	<p>SP003</p>	<p>Cable for transmitter adjustment via USB port - for models Tx11x, Tx21x with analog outputs and models Hxx2x, H306x.</p>
	<p>F8000</p>	<p>Solar radiation shield for transmitters with T+RH probe on a cable.</p>

OPTIONAL ACCESSORIES FOR HUMIDITY TRANSMITTERS



	Order code F5200	grey sensor cover with filter from stainless steel mesh, filtering ability 0,025mm
	F5200B	black sensor cover with filter from stainless steel mesh, filtering ability 0,025mm
	F0000	spare sintered bronze sensor cover; filtering ability 0.025mm.
	PP4	flat plastic circular flange for duct mounting
	PP90	right-angled stain-less steel flange for wall mounting
	SP004	plastic gland for direct mounting of the humidity probe to a 29 mm diameter hole
	SP005	tool for easy wire connection to WAGO terminals Wago - for transmitters with current and voltage output
	SP006	tool for easy wire connection to WAGO terminals Wago - for Txxx transmitters with serial output RS485 and RS232 and Hxxx transmitters
	MDO36	self adhesive Dual Lock for easy installation
	A1515	ac/dc adapter 230V-50Hz/12Vdc for Ethernet transmitters Tx5xx, Hx531 - with co-axial connector
	A1510	ac/dc adapter 230V-50Hz/12Vdc for serial output Txxx transmitters and Hxxx transmitters - for connection to terminals
	MDO46	ACCESSORIES FOR EASY RELATIVE HUMIDITY CALIBRATION AND ADJUSTMENT anodized duraluminum vessel for relative humidity calibration and adjustment
	HMO23	set of 5 humidity standards 10% RH with 5 application pads
	HMO24	set of 5 humidity standards 80% RH with 5 application pads